





Water Outlets Are Angled Like This From 1985 To 1988











CLUTCH LIFTER ROD PROBLEM



Wrong adjustment can wear the lifter rod making it flared and difficult to remove from case

www.millarengines.com





1984-85 - Due to the smaller shaft diameter at the clutch basket bearing, it is impossible to update the clutch without changing the transmission shaft to the 1986-2001 part #23210-ML3-000, bearing hub #22106-ML3-000, bearing #91021-ML3-003, washer #90457-ML3-000, and the basket, clutch hub combination that matches the case beeing used.

[Case dimensions limit updating a 1984 clutch to the 1986-1989 width basket] www.millarengines.com

